Report No. : HS1404020081A Version : A



CONTINUOUS IMMERSION AND DUST TEST REPORT

Company : <u>Taiway Electronics Components Co.</u>

Address : 4F., No. 4, 6, 8, Lane 359, Sec. 2, Zhongshan Rd., Zhonghe Dist.,

New Taipei City 23586, Taiwan (R.O.C.)

Sample Name : TK SERIES

Date Received : APR 02, 2014

Date Tested : APR 02, 2014 ~ APR 03, 2014

TESTING LABORATORY IS ACCREDITED BY:

IEC/IECQ 17025 certificate of independent test laboratory approval

Certificate No.: 1.72.0031

ISO 17025 accredited in respect of laboratory is approved by TAF

Certificate No.: L0835-120910

ISO 9001 certificate is approved by TUV CERT certification body of TUV NORD Cert GmbH

WE HEREBY CERTIFY THAT:

The test(s) shown in the attachment were conducted according to the indicating procedures. We assume full responsibility for the accuracy and completeness of these tests and vouch for the qualifications of all personnel performing them.

700700	Name	Signature	Date
Test Engineer	Gin Lu	Fin Lu	Apr 09, 2014
Manager	Longson Lin	Longson Lin	Apr 09, 2014

NOTE:

1. This report will be invalid if reproduced in part or altered in any way,

2. This report refers only to the specimen(s) submitted to test, and is intelled if used other

3. This report is ONLY valid with the examination seal and signature

 The tested specimen(s) will only be preserved for thirty days from collected by the applicant.

Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Tel: 886-3-579-9909, Fax: 886-3-610-0399

http://www.istgroup.com

Report No.: HS1404020081A

Page 1 of 12

TABLE OF CONTENTS

1. GENERAL INFORMATION	
1.1 DESCRIPTION OF UNIT	2
1.2 UNIT OPERATING CONDITION	2
2. CONTINUOUS IMMERSION TEST	
2.1 TEST EQUIPMENT	3
2.2 LABORATORY AMBIENCE CONDITION	
2.3 REFERENCE DOCUMENT	3
2.4 TEST CONDITION	3
2.5 SUMMARY OF TEST	3
3. DUST TEST	
3.1 TEST EQUIPMENT	4
3.2 LABORATORY AMBIENCE CONDITION	
3.3 REFERENCE DOCUMENT	4
3.4 TEST CONDITION	4
3.5 SUMMARY OF TEST	4
ATTACHMENTS	5



Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Tel: 886-3-579-9909, Fax: 886-3-610-0399

http://www.istgroup.com

Report No.: HS1404020081A

Page 2 of 12

1. GENERAL INFORMATION

1.1 DESCRIPTION OF UNIT

Manufacturer: Taiway Electronics Components Co.

Sample name: TK SERIES

Test item, Unit number and Sample quantity: (Total of 6 units)

Test item	Unit number	Sample quantity
Continuous immersion test	Unit no.1 to no.6	6 units
Dust test	Unit no.5 and no.6	2 units

1.2 UNIT OPERATING CONDITION

None



Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Tel: 886-3-579-9909, Fax: 886-3-610-0399

http://www.istgroup.com

Report No.: HS1404020081A

Page 3 of 12

2. CONTINUOUS IMMERSION TEST

2.1 TEST EQUIPMENT

Model	Calibration Date
ETL-L180 Water Leakage Test Chamber	NCR

2.2 LABORATORY AMBIENCE CONDITION

Temperature: 25 °C ± 5 °C

Relative humidity: 65 % ± 5 % (RH)

2.3 REFERENCE DOCUMENT

This test is based on IEC/EN 60529 IPX8 (2013) continuous immersion Test Protected.

2.4 TEST CONDITION

Units are non-operating.

The water temperature is +25 °C

The lowest point of unit is locating 1000 mm below surface of the water.

The duration of test is 60 minutes.

2.5 SUMMARY OF TEST

Before and after testing, units function was normal.

No permeating water the inner unit inspection will be performed by customer.



Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Tel: 886-3-579-9909, Fax: 886-3-610-0399

http://www.istgroup.com

Report No.: HS1404020081A

Page 4 of 12

3. DUST TEST

3.1 TEST EQUIPMENT

Model	Serial Number	Calibration Date
Vötsch- VDT 1000A	59566059640010	DEC 13, 2013

3.2 LABORATORY AMBIENCE CONDITION

Temperature: 25 °C ± 5 °C

Relative humidity: 65 % ± 5 % (RH)

3.3 REFERENCE DOCUMENT

The test is based on IEC/EN 60529 IP6X (2013) Dust Test Protected.

3.4 TEST CONDITION

Units are non-operating.

Dust material: Talcum powder (100% dry fine)

Particle size	Amount (%)
< 5 µm (Diameter)	42.31% ± 5
5~10 μm (Diameter)	35.85% ± 5
10~20 µm (Diameter)	21.15% ± 5
20~40 µm (Diameter)	0.69% ± 5
> 40 µm (Diameter)	0%

Amount of talcum power: 2 kg/m³ (chamber volume)

Dust density: 2.03 g/cm³
Depression level: 10 mbar

Air direction: Vertically to achieve slowest possible downward settlement

Duration of exposure: 8 hours

3.5 SUMMARY OF TEST

Before and after testing, units function was normal.

No permeating dust the inner unit inspection will be performed by customer.



Reliability & Failure Analysis Engineering Group
1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Tel: 886-3-579-9909, Fax: 886-3-610-0399

http://www.istgroup.com

Attachment 1: Photo of unit before all tests

Function was normal

Unit no.1





Report No.: HS1404020081A

Page 5 of 12

Unit no.2





Unit no.3







Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Tel: 886-3-579-9909, Fax: 886-3-610-0399

http://www.istgroup.com

Report No.: HS1404020081A

Page 6 of 12

Function was normal

Unit no.4





Unit no.5





Unit no.6








Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C. Tel: 886-3-579-9909, Fax: 886-3-610-0399 Report No.: HS1404020081A

Page 7 of 12

http://www.istgroup.com

Attachment 2: Photo of continuous immersion test setup







Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Tel: 886-3-579-9909, Fax: 886-3-610-0399

http://www.istgroup.com

Report No.: HS1404020081A

Page 8 of 12

Attachment 3: Photo of dust test setup

Unit no.5


Before testing





Depression level

After testing







Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Tel: 886-3-579-9909, Fax: 886-3-610-0399


http://www.istgroup.com

Report No.: HS1404020081A

Page 9 of 12

Unit no.6

Before testing





Depression level

After testing







Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C. Tel: 886-3-579-9909, Fax: 886-3-610-0399

http://www.istgroup.com

Report No.: HS1404020081A

Page 10 of 12

Attachment 4: Photo of unit after continuous immersion test

Function was normal


Unit no.1






Unit no.2





Unit no.3







Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Tel: 886-3-579-9909, Fax: 886-3-610-0399

http://www.istgroup.com

Report No.: HS1404020081A Page 11 of 12

Function was normal

Unit no.4






Unit no.5





Unit no.6







Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C. Tel: 886-3-579-9909, Fax: 886-3-610-0399

http://www.istgroup.com

Report No.: HS1404020081A

Page 12 of 12

Attachment 5: Photo of unit after dust test


Function was normal

Unit no.5





Unit no.6





<< The Following Blank >>